

North America Emission Control Area Fuel Oil Non-Availability Report

ECA0100

1

2

3

##

##(Include Double Pound for comments, not form fields)

##Report Form ID

Ship Operator Name Vessel Name

ID WALLEM

BERING ID

4

5

6

7

8

Flag Country	IMO ID Number	Date of ECA First Notice	Location of ECA First Notice	Name of Ports after First Notice
PANAMA	9146807	25-Jul-13	AT SEA	YOSU

Name of Last Port before ECA Entry
YOSU

Name of Port with Fuel Oil Supply Disruption
YOSU

11

12

13

Name of Original Fuel Supplier with Disruption
O.W. BUNKER AND TRADING A/S, COPENHAGEN

Number of Fuel Suppliers Contacted
4570151504

Date of Entry in the ECA
16-Aug-13

14

15

16

Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion
1100LT	2.30%(mass)	72h

Name of First POC	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?
Vancouver, Washington	yes	yes

20

21

22

Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?
1	nil	nil

Plan to Bunker Compliance Fuel Oil at Second POC?

nil

Number of Fuel Suppliers Contacted at the Second POC?

nil

25

26

27

Date of Exit from ECA?	Time of Exit from ECA?	Has this vessel operated in the ECA in previous 12 months?
23-Aug-13	1200lt	yes

28

29

30

Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?
2	2	no

Number of Submitted Reports	Designated Corporate Official Name
2nd	Pacific northwest ship and cargo services,(USA) INC

Designated Corporate Official E-mail	Designated Corporate Official Phone Number
<u>pnw-portland@pnwship.com</u>	13605735465

Description of Actions to Achieve Compliance
BUNKER ARRIVAL